

Vapor Port and Lysimeter valve connection box.




Type B Probe being  
driven into Subsurface  
Disposal Area (SDA)  
with the assistance of the  
ResonantSonic Drill Rig.



Workers attaching  
probe valve  
connection box.









Worker attaching  
Vapor Port probe  
cable prior to  
completion of  
installation.

